


## N plug connector assembly instructions

Specificatin No.	Connector	Cable type	
SH990726-01	AN-358P, AN-500P	SC-358/50 , SC-500/50 series	

Supplied parts



Dielectric



Body





Center pin


## 1. Strip cable

(1) Strip center conductor to dimension shown. Do not damage center conductor. Cut cable end needs to be plain.

- 2. Soldering center pin
  - (1) Insert center conductor of the cable into center pin until firmly fixed.
  - (2) Solder center conductor of the cable and center pin. Try to solder in a short time.
- (3) Check at part A & B, uniformly and adequately soldered.
- 3. Clean rosin flux
- 4. Soldering connector body
  - (1) Fix position of face  $^{\prime\prime}C^{\prime\prime}$  of center pin and face  $^{\prime\prime}D^{\prime\prime}$ of connector body as enlarged diagram.







1/2

Date	Drawn	Checked	Approved
1999.7.26	Kasai	Seino	Kasai

<sup>\*</sup> Please try to solder in a short time.

Specification No.	Connector		Cable type	
SH990726-01	AN-358P, AN-500P		SC-358/50 , SC-500/50 series	
<ul> <li>(2) Solder connector body and cable as diagram. Soldering needs to be short time and avoid excessive heat.</li> <li>(3) Inspect solder covers part E uniformly.</li> <li>5. Clean rosin flux</li> </ul>		E		
6. Insertion of dielectric  (1) Inspect inside of connector body is clean and dry before insertion.  (2) Insert dielectric into connector body.				
(2) Insert dielectric into connector body.  (3)Adherence to steps given will yield tolerance shown.			Dielectric	
			REF PLANE	

2/2