


## COAX CO., LTD. SMA jack connector assembly Instructions

Specification No.	Connector	Cable type
SH080131-01	AX-119J-NM	SC-119/50 series

Supplied parts





Dielectric

Connector body

Center contact


Insulator


## 1. Strip cable


 Remove cut outer conductor and dielectric from cable per diagram. Do not damage center conductor and cut cable end needs to be plain.


- 2. Insert stripped cable into connector body.
- 3. Soldering of center contact
  - Insert insulator onto exposed center conductor of cable, then insert center contact and fix the position.
  - (2) Solder center coductor and center contact.

    Try to solder in a short time.
  - (3) Check part "A" uniformly and adequately soldered.
- 4. Clean rosin flux









1/2

※ Please try to solder in a short time.

Date	Approved	Checked	Drawn
'08.01.31	Kasai	Seino	Kasai

Specification No.	Connector	Cable type
SH080131-01	AX-119J-NM	SC-119/50 series

## 5. Soldering connector body

- Set position of tip of center contact "C" and connector body "D" as shown in the enlarged diagram "a".
- (2) Solder connector body and cable with fixed position. Try to solder in a short time.
- (3) Inspect solder covers part "E" uniformly.
- 6. Clean rosin flux

## 7. Insertion of dielectric

- (1) Inspect inside of connector body is clean and dry before insertion.
- (2) Insert dielectric into connector body. Set the position of dielectric face "F" and connector body "D" as enlarged diagram "b".
- Recommended dielectric insertion tool
   BL98-5215-02 (Orient Microwave Corp.)

